

Message Text

LIMITED OFFICIAL USE

PAGE 01 SAN SA 04700 071509Z
ACTION SY-05

INFO OCT-01 ARA-10 ISO-00 /016 W
-----001338 080559Z /15
R 071420Z SEP 78
FM AMEMBASSY SAN SALVADOR
TO SECSTATE WASHDC 9509

LIMITED OFFICIAL USE SAN SALVADOR 4700

DEPT FOR A/SY/OPS/FO

E.O. 11652: N/A
TAGS: ASEC ES
SUBJ: SY FOLLOW-CAR PARTS NEEDED (77 PLYMOUTH FURY)

IN ORDER TO ADEQUATELY REPAIR DAMAGED FOLLOW-CAR, THE FOLLOWING
PARTS ARE NEEDED:

RIGHT FRONT DOOR
WINDOW FOR RIGHT FRONT DOOR
NECESSARY HINGES FOR RIGHT FRONT DOOR
MOLDING FOR ENTIRE RIGHT FRONT DOOR FRAME
THE REAR-VIEW MIRROR FOR RIGHT FRONT DOOR
THE SIDBOARD (MUD-GUARD) FOR RIGHT FRONT DOOR AREA
THE NECESSARY CLIPS TO ATTACH THE ABOVE
MOLDING FOR THE RIGHT PART OF FRONT WINDSHIELD
LOCK AND KEY FOR RIGHT FRONT DOOR
THE MOLDING FOR THE RAIN GUTTER/RUNER FOR RIGHT SIDE

AND CLIPS
INTERIOR MILDING FOR SIDBOARD (MUD-GUARD) AND
ALUMINUM STEP INTO RIGHT FRONT
FRONT WINDSHIELD

THIS IS IN ADDITION TO EXPENSIVE REPAIR TO FRAME AND BODY
LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 SAN SA 04700 071509Z

WHICH CAN BE MADE LOCALLY. REQUEST FISCAL DATA FOR
PAYMENT.
DEVINE

LIMITED OFFICIAL USE

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 07 sep 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 20 Mar 2014
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978SANS04700
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D780365-0790
Format: TEL
From: SAN SALVADOR
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780993/aaaacyvi.tel
Line Count: 58
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 2dfa6856-c288-dd11-92da-001cc4696bcc
Office: ACTION SY
Original Classification: LIMITED OFFICIAL USE
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: LIMITED OFFICIAL USE
Previous Handling Restrictions: n/a
Reference: n/a
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 14 jul 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 1518231
Secure: OPEN
Status: NATIVE
Subject: SY FOLLOW-CAR PARTS NEEDED (77 PLYMOUTH FURY) IN ORDER TO ADEQUATELY REPAIR DAMAGED FOLLOW-CAR, THE FOLLOWING PARTS ARE NEEDED
TAGS: ASEC, ES
To: STATE
Type: TE
vdkgvwkey: odb://SAS/SAS.dbo.SAS_Docs/2dfa6856-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014